



MICROCOPY RESOLUTION TEST CHART NATIONAL BUREAU OF STANDARDS-1963-A

AD




MEMORANDUM REPORT BRL-MR-3454

AD-A159

WEDGES USED FOR FILM CASSETTE PROTECTION

Gary L. Boyce

July 1985





APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED.

US ARMY BALLISTIC RESEARCH LABORATORY ABERDEEN PROVING GROUND, MARYLAND

Destroy this report when it is no longer needed. Do not return it to the originator.

Additional copies of this report may be obtained from the National Technical Information Service, U. S. Department of Commerce, Springfield, Virginia 22161.

The findings in this report are not to be construed as an official Department of the Army position, unless so designated by other authorized documents.

The use of trade names or manufacturers' names in this report does not constitute indorsement of any commercial product.

SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

REPORT DOCUMENTATION	PACE	READ INSTRUCTIONS
T. REPORT NUMBER	BEFORE COMPLETING FORM	
		. 3. RECIPIENT'S CATALOG NUMBER
MEMORANDUM REPORT BRL-MR-3454	AD-A15932	<u>B</u>
4. TITLE (and Subtitie)		5. TYPE OF REPORT & PERIOD COVERED
WEDGES USED FOR FILM CASSETTE PROT	he am t au	!
MEDGES OSED FOR LITTL CHOSELLE LEGIT	ECTION	
		6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(e)		8. CONTRACT OR GRANT NUMBER(#)
	1	o. cominger on contract transcaring
Gary L. Boyce		ļ
ł		
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
US Army Ballistic Research Laborat	ory	}
ATTN: AMXBR-TBD		1L162618AH80
Aberdeen Proving Ground, MD 21005	5-5066	1
11. CONTROLLING OFFICE NAME AND ADDRESS		12. REPORT DATE
US Army Ballistic Research Laborate	ory	July 1985
ATTN: AMXBR-OD-ST		13. NUMBER OF PAGES
Aberdeen Proving Ground, MD 21005	-5066	21
14. MONITORING AGENCY NAME & ADDRESS(II different	! from Controlling Office)	15. SECURITY CLASS, (of this report)
		Unclassified
	,	15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)		
Approved for public release, dista	ribution unlimit	ed.
17. DISTRIBUTION STATEMENT (of the abetract entered i	in Block 20, if different fro	m Report)
18. SUPPLEMENTARY NOTES		
TO SOFT EMMENT TO LEE		
19. KEY WORDS (Continue on reverse side if necessary and	d identify by block number)	,
Plant where		

Flash X-RAY

Protection

Explosives

Wedges and Cones

Blast Pressures

Cassette

20. ABSTRACT (Continue on reverse side if necessary and identify by block number)

This report discusses the protection of flash x-ray film cassettes during explosive tests. The problem is to protect the x-ray film while placing a minimum amount of material in the path of the x-rays. This report demonstrates that using a hollow wooden wedge, with a 60° included angle, on the front of the cassette, dramatically reduces the damage to the cassette and film.

DD 1 JAN 73 1473

EDITION OF 1 NOV 68 IS OBSOLETE

UNCLASSIFIED

TABLE OF CONTENTS

	1	age
	LIST OF ILLUSTRATIONS	5
I.	INTRODUCTION	7
II.	EXPERIMENTAL SETUP AND RESULTS	7
III.	CONCLUSION	9
	ACKNOWLEDGEMENTS	11
	DISTRIBUTION LIST	1 Q

Accouston For	;
MA GRAMI	X
January de January de La Contraction de La Contr	
1	
orthution/	
11. 511ity	Codes
(11 and Christian)	
A-1	



3

PREVIOUS PAGE IS BLANK

LIST OF ILLUSTRATIONS

Figu	ire	Page
1	Film Cassette	. 13
2	Pentration Curve for 300 KV Flash X-Ray System - Model 43733A	. 14
3	Film Cassette without Wedge	. 15
4	Film Cassette with Wedge	. 16
5	Film Cassette in Chamber using 300 KV Flash X-Ray	. 17
6	Film Cassette in Chamber using Cone or Wedge.	. 18

I. INTRODUCTION

High voltage flash x-ray systems are frequently used for observing explosive events. During such tests the x-ray screen and film must be protected from the blast from the charge, but the areal density of the protection must be small enough so that the x-rays are not blocked. In outdoor ranges this problem is minimized, but not eliminated, by letting the cassettes move in response to the blast. In enclosed chambers the problem is more severe because the motion of the cassettes must be restricted. Tests in our blast chambers are usually performed with the object about 2 - 4m from the x-ray tubes and about 0.6m from the cassette which holds the screen and film. The standard x-ray cassettes, shown in Figure 1> consist of layers of aluminum, felt, foam, and a steel backing. They are typically 450mm by 530mm in area. Based on the Hewlett Packard Flash X-ray Manual, our 300kV flash x-rays will penetrate the equivalent of 50mm of aluminum at a distance of 3m. as shown in Figure > This means one can safely use 25mm of aluminum on the front of the cassette and still have some ability to penetrate the test Experience indicates that this is adequate to protect the cassette for explosive charges of up to 0.5kg, but it is inadequate for larger charges.

This report discusses the use of hollow wooden cones or wedges on the front of the cassette. The technique appears to offer excellent protection with a minimum of areal density. A similar technique, involving an aluminum cone, has been used at the Los Alamos National Laboratory. 1

II. EXPERIMENTAL SETUP AND RESULTS

Tests were performed in similar circumstances with and without wooden cones or wedges. The setup without the extra protection is shown in Figure 3; with the extra protection, it is shown in Figure 4. An explosive charge of 2 or 4kg was detonated 508mm above a cover plate which consisted of either 25mm of aluminum or 25mm of plywood. The cover plate was supported on its edges by a steel frame which rested on the floor of the blast chamber. The cover plate area was 450mm by 530mm. The wedges on cones were made of 19.6 or 25.4mm plywood and had an included angle of 60° , as shown in Figure 4.

The data is shown in Table 1. With a 60° cone, a 25mm aluminum cover plate was undamaged by a 4kg charge. Without a cone, even a 2kg charge caused unacceptable damage. However, plywood cover plates did not provide acceptable protection, even with a cone.



LASL Phermex Data, Vol I, Mader, Neal, and Dick.

Table 1. Experimental Results

SECTION CONTRACTOR SECTION CONTRACTOR SECTIONS FOR A CONTRACTOR CO

Damage to Cover Plate	No damage	25 - 31.25mm bend	Destroyed cover plate	No damage	25 - 31.25mm bend	Front bent 25 mm Did not spall	No damage	Excessive damage, alum plates would cause damage to screens
Angled Plywood Protector	60° Cone	No cone	eoo cone	eoo ooe	No cone	euo oog	egpew 09	No cone
Cylinder Comp-B charge	spunod ς•η	4.5 pounds	4.5 pounds	spunod 6	spunod 6	η•5 pounds	4.5 pounds	4.5 pounds
Cover Plate	7039 25 mm alum	7039 25 mm alum	25 mm plywood	7039 25 mm alum	25 mm alum	9 mm alum/1" plywood 3 mm alum	25 mm alum	9 mm alum/25 mm plywood/3 mm alum
	~	?		.	ۍ.	•	7.	&

III. CONCLUSION

A wooden cone or wedge provides considerable additional protection to a film cassette with a minimum of added areal density. This technique is being utilized in the blast chambers in Building 1186, as shown in Figures 5 and 6.

ないのできた。これのなかなは、これのないなど、自然なられては、自然なられない。

ACKNOWLEDGEMENTS

The author wishes to thank Dr. Robert Frey (BRL) and Mr. Al Kennedy (Hewlett Packard Representative) for their helpful discussions.




Figure 1. Film Cassette.




Figure 2. Penetration Curve for 300 KV Flash X-Ray System - Model 43733A.




Figure 3. Film Cassette without Wedge.





Figure 4. Film Cassette with Wedge.



AND KINDS DESCRIPTION OF THE PARTY OF THE PA

Figure 5. Film Cassette in Chamber using 300 KV Flash X-Ray.




Figure 6. Film Cassette in Chamber using Cone or Wedge.

DISTRIBUTION LIST

No. of Copies Organization

- 12 Administrator
 Defense Technical Info Center
 ATTN: DTIC-DDA
 Cameron Station
 Alexandria, VA 22304-6145
- 1 HQDA DAMA-ART-M Washington, DC 20310

THE PERSONAL PROPERTY.

- 2 Chairman
 DOD Explosives Safety Board
 ATTN: Dr. T. Zaker
 COL O. Westry
 Room 856-C
 Hoffman Bldg 1
 2461 Eisenhower Avenue
 Alexandria, VA 22331
- 1 Commander
 US Army Materiel Command
 ATTN: AMCDRA-ST
 5001 Eisenhower Avenue
 Alexandria, VA 22333-0001
- 1 Commander
 Armament R&D Center
 US Army AMCCOM
 ATTN: SMCAR-TSS
 Dover, NJ 07801-5001
- 1 Commander
 Armament R&D Center
 US Army AMCCOM
 ATTN: SMCAR-LCE,
 Dr. R. F. Walker
 Dover, NJ 07801-5001
- 1 Commander
 Armament R&D Center
 US Army AMCCOM
 ATTN: SMCAR-TDC
 Dover, NJ 07801

No. of Copies Organization

- Commander
 Armament R&D Center
 US Army AMCCOM
 ATTN: SMCAR-LCE, Dr. N. Slagg
 Dover, NJ 07801-5001
- 1 Commander
 Armament R&D Center
 US Army AMCCOM
 ATTN: SMCAR-LCN,
 Dr. P. Harris
 Dover, NJ 07801-5001
- 1 Commander
 US Army Armament, Munitions
 and Chemical Command
 ATTN: SMCAR-ESP-L
 Rock Island, IL 61299
 - 1 Director
 Benet Weapons Laboratory
 US Army AMCCOM, ARDC
 ATTN: SMCAR-LCB-TL
 Watervliet, NY 12189
 - ! Commander US Army Aviation Research and Development Command ATTN: AMSAV-E 4300 Goodfellow Boulevard St. Louis, MO 63120
 - Director
 US Army Air Mobility Research
 and Development Laboratory
 Ames Research Center
 Moffett Field, CA 94035
- 1 Commander
 US Army Communications Electronics Command
 ATTN: AMSEL-ED
 Fort Monmouth, NJ 07703

DISTRIBUTION LIST

No. of Copies Organization

- 1 Commander
 ERADCOM Technical Library
 ATTN: DELSD-L (Reports Section)
 Fort Monmouth, NJ 07703-5301
- Commander
 US Army Missile Command
 ATTN: AMSMI-R
 Redstone Arsenal, AL 35898
- 1 Commander
 US Army Missile Command
 ATTN: AMSMI-YDL
 Redstone Arsenal, AL 35898

TORROW TARGETON, ISSUED OF CONTROL OF TARGETON OF THE TORROWS WITHOUT THE SECRET SECRETARY INCOMESSES TORROWS IN THE TORROWS IN THE TORROWS OF THE TORROWS O

- 1 Commander US Army Missile Command ATTN: AMSME-RK, Dr. R.G. Rhoades Redstone Arsenal, AL 35809
- 1 Commander
 US Army Tank Automotive Command
 ATTN: AMSTA-TSL
 Warren, MI 48090
- 1 Director
 US Army TRADOC Systems
 Analysis Activity
 ATTN: ATAA-SL
 White Sands Missile Range,
 NM 88002
- 1 Commandant
 US Army Infantry School
 ATTN: ATSH-CD-CSO-OR
 Fort Benning, GA 31905
- 1 Commander US Army Development & Employment Agency ATTN: MODE-TED-SAB Fort Lewis, WA 98433

No. of Copies Organization

- 1 Commander
 US Army Research Office
 ATTN: Chemistry Division
 P.O. Box 12211
 Research Triangle Park, NC 27709-2211
- 1 Commander Office of Naval Research ATTN: Dr. J. Enig, Code 200B 800 N. Quincy Street Arlington, VA 22217
- 1 Commander
 Naval Sea Systems Command
 ATTN: Mr. R. Beauregard,
 SEA 64E
 Washington, DC 20362
- 1 Commander
 Naval Explosive Ordnance
 Disposal Facility
 ATTN: Technical Library
 Code 604
 Indian Head, MD 20640
- 1 Commander
 Naval Research Laboratory
 ATTN: Code 6100
 Washington, DC 20375
- 1 Commander Naval Surface Weapons Center ATTN: Code G13 Dahlgren, VA 22448
- 9 Commander
 Naval Surface Weapons Center
 ATTN: Mr. L. Roslund, R122
 Mr. M. Stosz, R121
 Code X211, Lib
 E. Zimet, R13
 R.R. Bernecker, R13
 J.W. Forbes, R13
 S.J. Jacobs, R10
 Dr. C. Dickinson
 J. Short, R12
 Silver Spring, MD 20910

DISTRIBUTION LIST

No. of No. of Copies Organization Organization Copies 4 Commander 1 Director Los Alamos Scientific Laboratory Naval Weapons Center ATTN: John Ramsey ATTN: Dr. L. Smith, Code 3205 Dr. A. Amster, Code 385 P.O. Box 1663 Dr. R. Reed, Jr., Code 388 Los Alamos, NM 87544 Dr. K.J. Graham, Code 3835 1 Director China Lake, CA 93555 Sandia National Lab ATTN: Dr. J. Kennedy 1 Commander Albuquerque, NM 87115 Naval Weapons Station NEDED ATTN: Dr. Louis Rothstein. Aberdeen Proving Ground Code 50 Yorktown, VA 23691 Dir, USAMSAA ATTN: AMXSY-D 1 Commander in Chief AMXSY-MP, H. Cohen US Atlantic Fleet ATTN: G-4 (NSAP) Cdr. USATECOM Norfolk, VA 23511 ATTN: AMSTE-TO-F Cdr, CRDC, AMCCOM, 1 Commander ATTN: SMCCR-RSP-A SMCCR-MU Air Force Rocket Propulsion Laboratory SMCCR-SPS-IL ATTN: Mr. R. Geisler, Code AFRPL MKPA Edwards AFB, CA 93523 1 AFWL/SUL Kirtland AFB, NM 87117 1 Air Force Armament Laboratory ATTN: AFATL/DLODL Eglin AFB, FL 32542-5000 1 Commander US Army BMD Advanced Technology Center ATTN: Dr. David C. Sayles P.O. Box 1500 Huntsville, AL 35804 1 Director Lawrence Livermore Laboratory University of California ATTN: Dr. M. Finger

P.O. Box 808

Livermore, CA 94550

USER EVALUATION SHEET/CHANGE OF ADDRESS

This Laboratory undertakes a continuing effort to improve the quality of the reports it publishes. Your comments/answers to the items/questions below will aid us in our efforts.

CARREL MANAGER, SECTION

ではないのかが、 このなりなりがあっていたのからのは、国際のからからなど、自然のないないのは、日本のような

1. BRL Rep	port NumberDate of Report	
2. Date Re	eport Received	
3. Does the other area	of interest for which the report will be used.)	or
	ecifically, is the report being used? (Information source, designedure, source of ideas, etc.)	
as man-hour	e information in this report led to any quantitative savings as fars or dollars saved, operating costs avoided or efficiencies achieo, please elaborate.	
	Comments. What do you think should be changed to improve future (Indicate changes to organization, technical content, format, etc.	
	Name	
CURRENT	Organization	
ADDRESS	Address	
	City, State, Zip	
. If indicew or Corre	cating a Change of Address or Address Correction, please provide tect Address in Block 6 above and the Old or Incorrect address belo	he W.
	Name	
OLD ADDRESS	Organization	
	Address	
	City State 7in	

(Remove this sheet along the perforation, fold as indicated, staple or tape closed, and mail.)

	FOLD HE	RE — — — — -	
Director US Army Ballistic Research I ATTN: AMXBR-OD-ST Aberdeen Proving Ground, MD	-		NO POSTAGE NECESSARY IF MAILED IN THE UNITED STATES
OFFICIAL BUSINESS PENALTY FOR PRIVATE USE, \$300	BUSINESS R	EPLY MAIL 0 12062 WASHINGTON, DC	
	POSTAGE WILL BE PAID BY	DEPARTMENT OF THE ARMY	
US A	ector Army Ballistic Resea N: AMXBR-OD-ST rdeen Proving Ground		
	— FOLD HERE		

CONTROL CONTRO

END

FILMED

11-85

DTIC